Calvert Area
Liaison Meeting

12th March 2021

Chris James EKFB

Simon Griffiths Fusion

Thaina Sa'id EWR



Agenda

- 1. EWR Update (20 minutes)
- 2. EKFB Update (30 minutes)
 - a. Update on meeting with EKFB Project Director
 - b. Overview of works
 - c. Update on batching plant
 - d. Environmental update on vegetation clearance.
- 3. Fusion update (20 minutes)
- 4. AOB & next meeting

EKFB Main Works Update

Operational Overview

EKFB


- 1. Compound & Infrastructure
- 2. Aggregate delivery by Rail next step FCC
- 3. Ground investigation & underground services


Fusion

- 4. Archaeology
- 5. Woodland translocation & planting
- 6. Works Compound
- 7. Underground Services

EWR

8. Road Closures








2021

- OXD / MCJ4 LINE
 - East West Rail OB
 - Charndon Lodge UB
 - Pumping Station
 - Addison Road
 - East West Rail Culvert
 - IMD West + East Culvert
- > HS2 LINE
 - Perry Hill OB
 - West Street OB



Compound

Trial Holes

- Late March
- 66, 66A, 64C, 64, 65(2)



Road Closure Strategy

- West Street, long term to build bridge.
- Gawcott road. Traffic lights, crossing, short term closures for tie in work.







Road Crossing



Temporary Bridge







Concrete Batching Plant

Concrete Batching Plant – Key Information

Timeframe

March / April Compound set up, civils work.

May – July Assemble batching plant

August Concrete ready

Operational Levels

- 30 staff and welfare for 50 people
- 4 silos
- Eiffage Infrastructure Mobile Equipment




Sectioned site for priorities



Sectioned site for priorities

Carpark Low priority



Batching Plant

Priority work. Land available March

Land available April

Community Aspects

Visual Silo colours

• **Noise** White noise to permanent plant

Layout

Monitoring

Dust Sealed system

Lighting Design


Downward facing

Low level


PIR's







Containerised modules pulled out on skids to be lifted to final position










Lifting operation for the machine







Silo assembly sequence




Steel gantry support and cone constructed at ground level and lifted to position. Constructed porizontal to be lifted by 2 cranes



Silo top cone assembled first and lifted by crane. Lower rings bolted to top section in order and keep lifting and fitting a ring. 7 rings in total







Full 7-ring silo top lifted to top of steel gantry & cone and fitted to position

top-and-tail

Office / welfare setup

- 2-storey office/ welfare block
- Office space for 30 people
- Changing / welfare for 50 people
- Additional single office for batching plant operators
- Additional materials testing lab on site





Traffic

March – Last 2 weeks

Increase in EKFB HGV Traffic Daily Deliveries


- 1. West Street 20 / 30 deliveries daily
- 2. School Hill 20 now reaching maximum capacity
- 3. Shipton Lee some days at maximum



Rail Deliveries

Aggregate

- Now three daily rail deliveries.
 Equivalent to 240 HGV's every day.
- 2. Plans to set up rail head at FCC location




Section 61

Section 61 Agreements

Number and duration

- 1. Two covering Calvert Area
- 2. Six month period



EKFB HS2 Enquiries Update

Internal challenges



VEHICLES WITHOUT HS2 IDENTIFIERS – 1% OF HGVS



VEHICLES NOT FOLLOWING CORRECT ROUTES



INCREASED
PROTESTOR ACTIVITY
IN BUCKS



HGV DRIVERS
SPEEDING AND
DRIVING
INAPPROPRIATELY



MUD ON ROAD COMPLAINTS HAVE DECREASED – INCREASED ROAD SWEEPING Since our last meeting we received...
7 complaints

Cottage

The Rickyard

School Hill

Charndon


HGV driving inappropriately


7 complaints2 enquiries

1 of these did not related to EKFB works (street lighting)

6 of these were closed by EKFB, 2 remain open.

By category:





What are we doing to resolve complaints?



Aggregate deliveries – working closely with logistics team, ensuring offloading does not start until 8am at weekends



HGVs on unapproved routes - Ensuring drivers are issued with stop notices until they can explain why they did not follow approved route



driver training to the entire supply chain. Suppliers must enrol all drivers on this.



Dedicated Traffic Safety Control Officer to carry out more frequent checks and surveys to monitor HGVs

Calvert Area
Liaison Meeting

12th March 2021

Chris James EKFB

Simon Griffiths Fusion

Thaina Sa'id EWR

